

Circular Letter No. 481

December 19, 2018

TO ALL BRITISH COLUMBIA LAND SURVEYORS

RE: Reporting Damaged or Destroyed Integrated Survey Area Control Monuments

In accordance with Survey and Plan Rule 2-3(2), land surveyors must promptly report a damaged or destroyed Integrated Survey Area Control Monument in the manner required by the Surveyor General.

Damaged or destroyed Control Monuments are to be reported directly to Geographic Data & Services (GeoBC) within the Ministry of Forests, Lands, Natural Resource Operations and Rural Development using the online Survey Monument Condition Report form available from the main <u>MASCOT</u> webpage. The link can be found under Survey Utilities as "<u>Submit a Survey Monument</u> <u>Condition Report</u>".

Additionally, the Surveyor General also requests that land surveyors report damaged or destroyed control monuments that lie outside of Integrated Survey Areas, although no rule makes this a requirement at present.

This reporting by users will assist in maintaining an accurate inventory that is of benefit to all users and stakeholders of the monumented control system within the Province of BC.

Yours sincerely,

Tichal & Thomas

Mike Thomson, BCLS Surveyor General of British Columbia

Land Title and Survey Authority of British Columbia Suite 200 - 1321 Blanshard Street, Victoria, BC V8W 9J3 Phone: 1 877 577 5872 www.ltsa.ca