

CIRCULAR LETTER NO. 481A

(This letter supersedes Circular Letter No. 481)

March 30, 2026

TO ALL BRITISH COLUMBIA LAND SURVEYORS

**Re: Reporting Damaged or Destroyed Integrated Survey Area Control
Monuments**

In accordance with Survey and Plan Rule 2-3(2), land surveyors must promptly report a damaged or destroyed Integrated Survey Area Control Monument in the manner required by the Surveyor General.

Damaged or destroyed Control Monuments are to be reported directly to GeoBC within the Ministry of Water, Land and Resource Stewardship using the Condition Report template available from the [GeoNetBC](#) website. Specific information for submitting a monument condition report can be found on GeoNetBC's "[Monument Condition Reports](#)" subpage.

Additionally, the Surveyor General also requests that land surveyors report damaged or destroyed control monuments that lie outside of Integrated Survey Areas, although no rule makes this a requirement at present.

This reporting by users will assist in maintaining an accurate inventory that is of benefit to all users and stakeholders of the monumented control system within the Province of BC.

Yours sincerely,

Cristin Schlossberger, BCLS
Surveyor General of British Columbia